

COMPATIBILITY TABLE FOR SENSORS AND POWER SUPPLY UNITS DINEL

Sensors and output types \ Supply units	MGU-800	PCU-100	PDU-4xx	SSU-1211/2411	DSU-1222/2422	LCU-1221/1232	TDU-1211/1222	DSU-1222-A/AP	SSU-1212-D/AD	DSU-1222-W	SDSU-1222-W	NSU-811/812	NDSU-822	NLCU-821/822	SPSU-1200-20	SPSU-2400-18	PSU-1200-S	PSU-2400-S	IRU-420-I/U/H	FCU-400	CDSU-522	LDU-401	UHC-01	URC-485	UCC-01			
Continuous level meters																												
ARLM-70	I	x	x	x													x		x					x				
ARLM-54	I	x	x	x													x		x					x				
CLM-70	I	x	x	x													x		x					x				
GRLM-70	I	x	x	x													x	x	x	x				x				
	M	x																							x			
ULM-70	I	x	x	x													x	x	x	x				x				
	M	x																							x			
ULM-54	I	x	x	x													x	x	x	x				x				
ULM-53	I	x	x	x													x	x	x	x				x				
	U	x		x													x	x	x	x				x				
	M	x																							x			
DLM-35	I	x	x	x													x	x	x	x	x							
	U	x		x													x	x	x	x	x							
CLM-36	I	x	x	x													x	x	x	x	x			x				
	U	x		x													x	x	x	x	x			x				
CLM-40	I	x	x	x													x	x	x	x	x							
	U	x		x													x	x	x	x	x							
	CAN																								x			
HLM-25S	I	x	x	x													x	x	x	x								
	U	x		x													x	x	x	x								
HLM-35	I	x	x	x													x	x	x	x								
	U	x		x													x	x	x	x								
HLM-25C	I	x	x	x													x	x	x	x								
	U	x		x													x	x	x	x								
HLM-16N	I	x	x	x													x	x	x	x								
	U	x		x													x	x	x	x								
HLM-25N	I	x	x	x													x	x	x	x								
	U	x		x													x		x	x								
Flowmeters																												
TFS-35	PFPT				x	x	x	x	x							x	x	x	x									
	IFPF	x	x	x													x	x	x	x								
	IFPT	x	x	x													x	x	x	x								
EFM-115																	x	x	x	x							x	
Pressure sensors																												
PPM-35	I	x	x	x													x	x	x	x				x				
Oil quality sensors																												
QOS-35	U	x		x													x	x	x	x								

Suitable combinations are marked x.

COMPATIBILITY TABLE FOR SENSORS AND POWER SUPPLY UNITS DINEL

Sensors and output types \ Supply units	MGU-800	PCU-100	PDU-4xx	SSU-1211/2411	DSU-1222/2422	LCU-1221/1232	TDU-1211/1222	DSU-1222-A/AP	SSU-1212-D/AD	DSU-1222-W	SDSU-1222-W	NSSU-811/812	NDSU-822	NLCU-821/822	SPSU-1200-20	SPSU-2400-18	PSU-1200-S	PSU-2400-S	IRU-420-I/U/H	FCU-400	CDSU-522	LDU-401	UHC-01	URC-485	UCC-01				
Limit level sensors																													
RFLS-24 P				x x x x x x						x					x x x x x														
ULS-53 P				x x x x x											x x x x x														
	S			x x x x											x x x x x														
RFLS-35 P				x x x x x						x					x x x														
	R			x x											x x x														
	PD							x							x x														
RFLS-28 P				x x x x x					x x						x x x x x														
	PD							x x							x x x x x														
DLS-35 N				x x x x x						x					x x x x x														
	P			x x x x x											x x x x x														
	R			x x											x x x														
DLS-27 N				x x x x x					x						x x x x x														
	P			x x x x x					x x						x x x x x														
	R			x x											x x x x x														
RFLS-53 P				x x x x x											x x x x x														
	RE																												
	SSR																												
CLS-23 P				x x x x x					x						x x x x x														
	S			x x x x											x x x x x														
	R			x x											x x x x x														
CLS-23S S				x x x x					x						x x x x x														
GPLS-25 P				x x x x x											x x x x x														
	S			x x x x											x x x x x														
FLD-32 S				x x x x				x						x	x x x x x														
CPS-24 N				x x x x x					x						x x x x x														
	P			x x x x x				x						x	x x x x x														
	R			x x										x	x x x														
FS-4														x															
CNP-18																													x
CTS-41																			x x x x x										

Suitable combinations are marked x.

